

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School : **Shifaly International School,**
2. Location : **Rahon Road, Ludhiana**
3. Plot Area : **10047 Sq. Yard**
4. Plinth Area : **G.F.13238' F.F.12550' S.F.122 50' T.F.12250' F.F. 4334.25**
5. Number of Story: **G + Three**
6. Year of Construction of Building :
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given :
 - a) Name of the Engineer with qualification : **as per drawing**
 - b) Address of Engineer : **as per drawing**
 - c) Set of Structural drawings used in the construction, if available : **as per drawing**
 - d) Name & address of Architect with qualification :
8. **Whether the building has been constructed for the purpose** :
 - a) School : **YES**
 - b) Residential Purpose and converted for use as a School : **NO**
9. **Materials used for roofs**
 - a) R.C.C. Slabs : **YES**
 - b) R.S. Joist & Buttons : **NO**
 - c) Wooden joists & Buttons : **NO**
10. **Materials used for walls**
 - a) Mud Mortar : **NO**
 - b) Cement Mortar : **YES**
 - c) Lime Mortar : **NO**
11. **Flooring**
 - a) Conglomerate : **NO**
 - b) Terrazzo/Marble : **YES**
 - c) Brick Paving. : **NO**
12. **A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows (Attached)**

Rosy Jain

Principal
Shifaly International School
Affiliated to C.B.S.E. Affiliation No. 1630495
Exam School Code : 20495
Rahon Road, Ludhiana

Signature with Stamp of the
seat of the School/Institution.

PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 01/8/2022..... And have Visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use up to (indicate up to which it can be used) 31/3/2023.....



Sub Divisional Engineer

Sub Divisional Engineer,
Provincial Sub Division No. 3,
P.W.D. B&R, Br. LUDHIANA.



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- eepdldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਸਿਵਾਲੀ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ
ਰਾਹੋਂ ਰੋਡ, ਲੁਧਿਆਣਾ।

ਨੰ. 1694

ਮਿਤੀ: 10/8/22

ਵਿਸ਼ਾ:-

Request letter for issuance of building safety certificate

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਸਿਵਾਲੀ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ, ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2023 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮੰਨਜ਼ੂਰੀ ਤੋਂ ਬਗੈਰ ਕੋਈ ਵੀ ਐਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

H. S. Dhillon
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ. ਨਿ. ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।
9/8/22

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 385 ਮਿਤੀ 2/08/2022 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

H. S. Dhillon
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ. ਨਿ. ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।